

BSC CHEMICALS cc

MANUFACTURERS OF PROPRIETARY CLEANING PRODUCTS

Reg No. CK 89/11226/23

PO Box 44 Robertson Western Cape South Africa 6705 Tel: +27 (023) 626 2873 Fax: +27 (023) 626 2874 Email: bscchems@mweb.co.za Web: www.bscchemicals.co.za



STAR SOLVE

[Solvent Degreaser, Tar and Spot Remover]

INTRODUCTION

STAR SOLVE is a versatile, safe cold cleaner that has wide range of industrial applications. It combines an optimum of physical properties with a high level of safety. STAR SOLVE is a solvent degreaser and tar cleaner for maximum grease, heavy soil and excess tar removal. Its high flash point makes it ideal for cleaning and degreasing in mining institutions, vehicle workshops, garages and road maintenance depots. This product is also excellent for cleaning glue, gum, etc. from vinyl and other surfaces. Before using on painted surfaces, compatibility tests should be performed.

ADVANTAGES

- Versatile
- High flash point
- Fast dissolving action
- Safe on all common metals
- Neutral pH

APPLICATIONS

STAR SOLVE cleans products and machinery safely and effectively. It is especially appropriate for in place and bench spray cleaning of electrical motors and generators. Other cleaning applications include business machine parts, hydraulic systems, air filters and air conditioning equipment, refrigeration equipment, traffic signal boxes, wrapping machines; bowling equipment; moulds, typewriter carriages, potting compounds and printing press rolls.

OPERATING DATA

Operating conditions

Operating temperature : Ambient

Contact time : As required to loosen soil Equipment : Mild steel or plastic

DILUTION Use **AS IS**

METHOD

Dip : For routine maintenance & bench cleaning as well as

cleaning during and after fabricating. To minimize evaporation, cover containers when not in use.

For enhanced cleaning of small to medium sized parts by cavitations STAR SOLVE is the ideal organic fluid for ultrasonic applications because of its low surface tension, low vapour pressure and low specific gravity. An ultrasonic cleaning frequency of 20-25 kc is optimum. Optimum bath temperature is approximately 54° to 60°C.

Wipe-on, wipe-off : For general equipment cleaning. Use clean cloths.

Spray : For hard-to-get-at surfaces. Spray undiluted STAR

SOLVEE with coarse jet or spray pattern so that solvent is not atomized. Spray pressure should not exceed 20

psi.

CAUTIONS

Although STAR SOLVE is relatively safe with no hazardous implications, it is always advisable to take the necessary precautions as is with all Chemical Cleaning Products, e.g., be aware of relevant First Aid treatment; handle with care; wash hands after use and store in a cool and safe place.

WARRANTY

We warrant our goods to conform to our standard specifications. This warranty is in lieu of any and all other warranties or guarantees. Our obligation hereunder for breach of such warranty is limited to either refund of the purchase price or replacement of said product as we may elect. We make no other warranties, express or implied, including those of MERCHANTABILITY and FITNESS FOR A PARTICULAR PURPOSE.

We believe that the statements, technical information and recommendations contained herein are reliable, but are given without warranty or guarantee of any kind except as specified above. Beyond that specified above, we assume no responsibility for any loss, damage or expense, direct or consequential, arising out of the use of, or inability to use, our goods. Their quality and suitability for a particular purchase or use should be confirmed by the user's own tests.

STANDARD PACKAGES

1 Litre 2 Litre 5 Litre 25 Litre 200 Litre